



AutoCAD Common Shortcut Key (2D)

Draw

L	LINE
XL	CONSTURCTION LINE
PL	POLYLINE
POL	POLYGON
REC	RECTANG
A	ARC
C	CIRCLE
REVCLOUD	REVCLOUD
SPL	SPLINE
EL	ELLIPSE
I	INSERT BLOCK
B	DEFINE BLOCK
W	WRITE BLOCK
H	HATCHING
DT	TEXT (SINGLE LINE)
T	MTEXT (MULTILINE)

Modify

E	ERASE
CO	COPY
MI	MIRROR
O	OFFSET
AR	ARRAY
M	MOVE

RO	ROTATE
SC	SCALE
S	STRETCH
TR	TRIM
EX	EXTEND
BR	BREAK, BREAK AT POINT
J	JOIN
CHA	CHAMFER
F	FILLET
X	EXPLODE

Other Useful Command

PE	POLY EDIT
OP	OPTION
DI	DIST
AREA	AREA
MASSPROP	MASSPROP
LTSCALE	LINETYPESCALE
PSLTSCALE	PAPER SPACE LT SCALE
LA	LAYER
LI	LIST
Z	ZOOM
P	PAN
F3 KEY	OBJECT SNAP
F8 KEY	ORTHO
F10 KEY	POLAR



AutoCAD Common Shortcut Key (3D)

General & basic navigation

V	VIEW
SHA	SHADEMODE
3DO	3DORBIT
HIDE	HIDE
SHADE	SHADE
RE	REGEN
UCS	UCS
DDUCS	DDUCS

3D modeling

BOX	BOX
SPHERE	SPHERE
CYL	CLYINDER
CONE	CONE
WE	WEDGE
TOR	TORUS
EXT	EXTRUDE
REV	REVOLVE
3D	3D SURFACE

3D Modify

UNI	UNION
SU	SUBTRACT
IN	INTERSECT
SEC	SECTION

SL	SLICE
INF	INTERFERE
ROTATE3D	ROTATE 3D
MIRROR3D	MIRROR3D
AL	ALIGN
3DARRAY	3DARRAY
SOLIDEIDT	SOLIDEDIT

Lighting, Material and Rendering

MATLIB	MATERIAL LIBRARY
RMAT	MATERAIL
SETUV	UV MAP
LIGHT	LIGHT